

<b>BOBINE ACCENSIONE</b>	
<b>85.30530</b>	
NO PHOTO AVAILABLE 	Ford Focus III 2.0 ST L.Rover Freelander 2 2.0 Si4
	<b>Ford 5168444</b>
<b>85.30531</b>	
	Ford C-Max,Focus,Kuga 1.6 EcoBoost
	<b>Ford 1832313</b>
<b>85.30537</b>	
	Saab 9-5 (YS3E) 3.0 V6t
	<b>Saab 55561133</b>
<b>CORPI FARFALLATI</b>	
<b>88.001R</b>	
	FIAT DOBLO (119) 1.2 (223AXA1A) / PUNTO (188) 1.2 PANDA (141A_) 1100 / (169) 1.1-1.2 4x4 SEICENTO (187)1.1 LANCIA Y (840A) 1.2 / YPSILON (843) 1.2
	<b>FIAT 46781326, 71718959, 71787554, 77363298</b>
<b>88.084R</b>	
	FIAT BRAVO II (198) 1.9 D Multijet
	<b>FIAT 55200820, 55202662, 55229712</b>
<b>CORPI FARFALLATI</b>	

<b>88.090R</b>	
	ALFA ROMEO 159 (939) 1.9 JTDM 16V FIAT CROMA (194) 1.9 D Multijet OPEL ASTRA H (L48) 1.9 CDTI / SIGNUM 2.0 DTI VECTRA C / C GTS 1.9 CDTI / SAAB 9-5 (YS3E) 1.9 TiD
	<b>FIAT 55186521, 55196350, 55199971</b> <b>OPEL 5828246</b>
<b>88.141R</b>	
	ALFA ROMEO 147 (937) 1.9 JTD / 156 (932) / 166 (936) FIAT BRAVA (182) / BRAVO I (182) / MAREA (185) LANCIA LYBRA (839AX) / THESIS (841AX)
	<b>ALFA ROMEO 71793582</b> <b>FIAT 46767692, 46767695, 46791356, 46817372,</b> <b>46817373, 55222587, 73503063</b>
<b>88.196R</b>	
	OPEL AGILA (A) (H00) 1.0 12V-1.2 16V ASTRA G Caravan (F35_) / CC (F48_, F08_) / Stufenheck (F69_) 1.2 16V CORSA C (F08, F68) 1.0
	<b>Opel 825243, 9157512</b> <b>Bosch 0280750044</b>
<b>88.220</b>	
	Opel Astra J 1.7 CDTI
	<b>Opel 825021</b>
<b>88.221R</b>	
	FORD B-MAX (JK) 1.4-1.4 LPG FIESTA VI 1.25-1.4-1.4 LPG FOCUS II (DA_) 1.4 FUSION (JU_) 1.25-1.4-1.4 LPG-1.6
	<b>Ford 1538498, 1745465</b> <b>Bosch 0280750533</b>
<b>CORPI FARFALLATI</b>	

<b>88.224</b>	
	BMW 1 (F20) 116 i Mini (F55) One
	<b>BMW 13547618838</b>
<b>88.250R</b>	
	SMART (MCC) CABRIO (450) 0.6-0.7 CITY-COUPÉ (450) 0.6-0.7 / CROSSBLADE (450) 0.6 FORTWO Cabrio (450) 0.7 / FORTWO Coupe (450) 0.7 ROADSTER (452) 0.7 / ROADSTER Coupe (452) 0.7
	<b>SMART (MCC) 0003094V004, 0003094V006,                      0003094V007, A0003094V004, A0003094V006,                      A0003094V007</b>
<b>88.251R</b>	
	FORD C-MAX II 1.6 / FIESTA VI 1.0 EcoBoost-1.6 Ti / FOCUS III 1.6 / GALAXY (WA6) 1.8 TDCi / MONDEO IV (BA7) 1.6 Ti / S-MAX (WA6) 2.0-2.0 Flexifuel-2.5 ST
	<b>Ford 1716693</b>
<b>ELETTROINIETTORE</b>	
<b>81.419</b>	
	Chevrolet Cruze, Orlando 1.8
	<b>Opel 55353803                      VDO A2C59516770</b>
<b>POMPE CARBURANTE</b>	
<b>70195</b>	
	Perkins, Massey Ferguson
	<b>Massey Ferguson 4132A014                      Perkins 17/927800</b>
<b>POMPE CARBURANTE</b>	

<b>70196</b>	
	Caterpillar, Massey Ferguson
	<b>Caterpillar 4132A015</b>
<b>INDICATORE LIVELLO</b>	
<b>71294</b>	
	HYUNDAI ACCENT III (MC) 1.5 CRDi GLS
	<b>HYUNDAI 311101G800</b>
<b>IMP. ALIMENTAZIONE CARBURANTE</b>	
<b>72885</b>	
	Fiat Panda (169) 1.2 4x4/N.Power
	<b>Fiat 51806987</b>
<b>MISURATORI MASSA ARIA</b>	
<b>38.960</b>	
	Hyundai Sonata V 2.0,2.4
	<b>Hyundai 2816425000</b>
<b>KIT</b>	
<b>84.2035</b>	
	KIT BRC GENIUS MAX

<b>84.2036</b>	
	KIT Landi LI02, LI03
<b>84.2037</b>	
	KIT Landi IG1
<b>84.2038</b>	
	KIT Lo-Gas 7R100002 Electronic
<b>84.2039</b>	
	KIT OMVL CPR-LPG Ulisse
<b>KIT</b>	
<b>84.2040</b>	
	KIT Tomasetto AT07

<b>84.2041</b>	
	KIT KME Red.1
<b>84.2043</b>	
	KIT Vialle D4-F4
<b>RAIL COMPLETO</b>	
<b>84.2044</b>	
	Rail completo Landi gpl VERDE
	<b>Landi Renzo 238210001</b>
<b>84.2045</b>	
	Rail completo Landi gpl NERO
	<b>Landi Renzo 238200001</b>
<b>RACCORDO RECUPERO GASOLIO</b>	
<b>81.426</b>	
	Kit raccordino ISUZU

<b>81.427</b>	
	<p>Kit raccordo ISUZU</p>
<b>81.428</b>	
	<p>Siemens 1 VIA a L</p>
<b>81.429</b>	
	<p>Siemens 2 VIE</p>
<b>81.430</b>	
	<p>Siemens 2 VIE a T</p>
<b>RACCORDO RECUPERO GASOLIO</b>	
<b>81.431</b>	
	<p>Siemens 2 VIE a V</p>

<b>81.432</b>	
	Siemens 2 VIE
<b>POMPA VUOTO</b>	
<b>89.259</b>	
	Kia Sorento
	<b>Kia 288104A400</b>
<b>POMPA ACQUA PULIZIA CRISTALLI</b>	
<b>5.5100</b>	
	Ford Fiesta III Mondeo II, Transit
	<b>Ford 1637624</b>
<b>SENSORE ALBERO A CAMME</b>	
<b>83.3213</b>	
	Chevrolet Cruze Opel Astra J 1.6,1.8
	<b>Opel 6235752</b> <b>Chevrolet 55565709</b>
<b>SENSORI DI PRESSIONE</b>	
<b>84.441</b>	
	BMW,PSA
	<b>BMW 13627599907</b> <b>PSA 1922W0</b>



<b>84.470</b>	
	Mazda 2 (DE) 1.3 3 (BL) 1.6 MZR
	<b>Mazda ZJ2018211</b>
<b>84.489</b>	
NO PHOTO AVAILABLE 	Toyota Yaris 1.4 D-4D Mini R50,R53) One D
	<b>Toyota 8942012220</b> <b>Mini 13627801387</b>
<b>84.490</b>	
	Toyota RAV4 III 2.2 D-4D Yaris 1.4 D-4D
	<b>Toyota 8942120200</b>
<b>84.491</b>	
	Subaru Legacy IV 3.0 R Toyota Yaris 1.3
	<b>Toyota 8942126030</b> <b>Subaru 22012AA200</b>
<b>SENSORE ALTA PRESSIONE CARBURANTE</b>	
<b>81.403</b>	
NO PHOTO AVAILABLE 	Renault Megane II 1.5 dCi
	<b>Renault 8200579287</b> <b>Siemens 5WS40208</b>

<b>SENSORI DI PRESSIONE GAS DI SCARICO</b>	
<b>84.439</b>	
	Mercedes A 180 CDI (W176) Sprinter (906)
	<b>Mercedes 6429050200</b>
<b>84.440</b>	
	Volvo V40, XC70 II D4
	<b>Volvo 31370160</b>
<b>SENSORE PRESSIONE CARBURANTE</b>	
<b>81.415</b>	
	Peugeot Citroen 1.4 /1.6 Hdi
	<b>PSA 9670076780</b>
<b>SENSORE TEMPERATURA DEL REFRIGERANTE</b>	
<b>82.329</b>	
	Audi A3 (8V1), VW Golf VII 1.6, 2.0 TDI
	<b>VAG 04E919501B</b>
<b>SENSORI TEMPERATURA GAS DI SCARICO</b>	
<b>82.148</b>	
	Chevrolet Captiva 2.0D Opel Antara 2.0 CDTI
	<b>Opel 4803538</b> <b>Chevrolet 96436268</b>

<b>82.149</b>	
	Chevrolet Captiva 2.0D Opel Antara 2.0 CDTI
	<b>Opel 4803539</b> <b>Chevrolet 96436269</b>
<b>SENSORE DI DETONAZIONE</b>	
<b>83.3243</b>	
	Chrysler Sebring Mitsubishi Carisma
	<b>Mitsubishi MD304933</b>
<b>SENSORE DI DISTANZA PERCORSO (ODOMETRO)</b>	
<b>83.3098</b>	
	Audi A3 (8L1) VW Golf IV
	<b>VAG 191919149E</b>
<b>SENORI GIRI PER CAMBIO AUTOMATICO</b>	
<b>83.3187</b>	
	Opel Signum Saab 9-5 (YS3E) 2.0 Turbo
	<b>Opel 1235276</b> <b>Saab 93191689</b>
<b>SENORI GIRI PER CAMBIO AUTOMATICO</b>	
<b>83.3198</b>	
	Toyota Corolla (E10) 1.6 RAV 4 II 2.0 VVTi
	<b>Toyota 8318112040</b>

<b>83.3236</b>	
	Fiat, Mitsubishi Nissan, Renault
	<b>Fiat 9948812</b> <b>Renault 7701065844</b>
<b>SENSORI VELOCITA VEICOLO</b>	
<b>83.3125</b>	
	Honda City Jazz II 1.3, 1.5
	<b>Honda 78410SAA003</b>
<b>83.3158</b>	
	Kia Sportage (JE, KM)
	<b>Kia 4362139700</b>
<b>83.3161</b>	
	Hyundai ix35 Kia Sportage 2.0 CRDi
	<b>Hyundai 4363024800</b>
<b>SENSORI VELOCITA VEICOLO</b>	
<b>83.3186</b>	
	Opel Movano, Vivaro 2.5 CDTI
	<b>Opel 4500692</b>

<b>83.3210</b>	
	LIFAN GROUP
	<b>LIFAN LF479Q53802100A</b>
<b>83.3239</b>	
	LIFAN GROUP
	<b>LIFAN LF481Q33802100C</b>
<b>83.3240</b>	
	LIFAN GROUP
	<b>LIFAN LF465Q5A3802100A</b>
<b>SONDA LAMBDA</b>	
<b>90472</b>	
	Renault Clio IV 1.5 dCi Nissan Qashqai 1.6 dCi
	<b>Renault 22 6A 472 92R</b> <b>Bosch 0 281 004 404</b>
<b>VALVOLA FILTRO GASOLIO</b>	
<b>81.257</b>	
	AUDI A3-A4 1.9 TDI SEAT IBIZA III (6K1) / LEON (1M1) / TOLEDO II (1M2) SKODA OCTAVIA (1U2) / SUPERB (3U4) VW BORA (1J2) / GOLF IV (1J1) / POLO (6N2)
	<b>VW / AUDI 1J0127247, 1J0127247A, 1J0127247E</b>

<b>VALVOLE EGR</b>	
<b>83.1045</b>	
	Ford Transit Connect S-Max (WA6) 1.8 TDCi
	<b>Ford 1668578</b>
<b>83.1062</b>	
	Hyundai i30 Kia Cee'd 1.4,1.6 CRDi
	<b>Hyundai 284102A300</b>
<b>83.1065</b>	
	Kia K2500, K2700
	<b>Kia 2846142610</b>
<b>83.1067</b>	
	Ssangyong Rexton
	<b>Ssangyong 6611403460</b>
<b>VALVOLE EGR</b>	
<b>83.1068</b>	
	Ssangyong Actyon, Kyron
	<b>Ssangyong 664140026A</b>

<b>83.1070</b>	
	Ssangyong Actyon, Korando
	<b>Ssangyong 6711400460</b>
<b>83.1074</b>	
	Kia Sportage
	<b>Kia 284102A850</b>
<b>83.1083</b>	
	Hyundai H-1 2.5 CRDi
	<b>Hyundai 284104A470</b>
<b>ELETTROVALVOLA DI CONTROLLO</b>	
<b>83.1038</b>	
	Opel Corsa E 1.3 CDTI
	<b>Opel 1302285</b>
<b>ELETTROVALVOLA SFIATO</b>	
<b>83.1055</b>	
	Audi A4 (8E2,B6) 1.8 T VW Golf V 1.4 TSI
	<b>VAG 1C0906517A</b> <b>Bosch 0280142353</b>